

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/21/2021

Submitted Date:

05/25/2021

Document Number:

696202713

**FIELD INSPECTION FORM**

Loc ID: 414132 Inspector Name: Trujillo, Aaron On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 77330  
Name of Operator: SG INTERESTS I LTD  
Address: 100 WAUGH DR SUITE 400  
City: HOUSTON State: TX Zip: 77007

**Findings:**

- 6 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		inspection@sginterests.com	<a href="#">All Inspections</a>
,		dnr_cogccenforcement@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414132	LOCATION	AC			-	Cow Skull 11-89-18 1	RI

**General Comment:**

On 05/21/2021, Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at SG Interests' Cow Skull 11-89-18 1 location in Gunnison County, Colorado. This inspection is a followup to inspection: #696201334 dated 5/26/2020, #696201673 dated 8/31/2020, #696202027 dated 11/19/2020, #696202531 dated 3/31/2021, and #696202648 dated 5/6/2021, to document compliance with the following corrective actions: 1002.f.(2)C: Stormwater 1003: Interim Reclamation

It was observed in this inspection that the Location remains out of compliance with COGCC Rules and corrective actions. Refer to the "Reclamation", "Stormwater" and "Good Housekeeping" section of this inspection report for additional details. Refer to the photo-documentation of the observed compliance issues attached to this report. Any corrective action(s) from previous inspections that have not been addressed are still applicable. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

WEEDS

Comment:

Inspection #696202648 observed noxious weeds on th slopes of the west end of the Location, and on the berm on the northwest end of the Location. Inspection required weed management by 6/7/2021.

Noxious weed management has not yet occurred; weeds remain evident. CA from Inspection #696202648 remains applicable.

Corrective Action:

Comply with Rule 1003.f. and Rule 606

Date: 06/07/2021

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 414132 Type: LOCATION API Number: - Status: AC Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: IMPROVED PASTURE, IRRIGATED, OTHER

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? Fail Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? Fail

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced Fail Recontoured Fail 80% Revegetation Fail

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? F

Comment Operator previously received an approved 502.b delayed operations interim reclamation waiver (Doc. #401721595). Sundry expired 2/5/2020 and reclamation was required. Previous inspections observed that reclamation of areas not needed for production on the Location has not been conducted in accordance with COGCC 1003 requirements. Inspection required Operator to comply with COGCC 1003 rules and conduct interim reclamation.  
  
It was observed in this inspection that reclamation work on areas not needed for production has not been conducted in accordance with COGCC Rules and Corrective actions.  
  
This corrective action has not been addressed and remains applicable.

Corrective Action Comply with COGCC 1003 rules and conduct interim reclamation. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of predisturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local soil conservation district. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed.

Date 02/05/2020

Overall Interim Reclamation Fail

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: IMPROVED PASTURE, IRRIGATED

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action: **Install or repair required BMPs in accordance with Rule 1002.f and good engineering practices; Maintain BMPs in proper functioning condition; Continue stormwater management until Location receives a passing final reclamation inspection, pursuant to Rule 1002.f.**  
  
**Interim reclamation due on the Location. Temporary stabilization controls will be required on areas to be interim reclaimed; Long term stabilization BMPs will be required on all areas not interim reclaimed.**

Date: 06/13/2020

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><b>STORMWATER COMMENT</b></p> <p>Previous inspection documented that control measures to manage runoff and stabilize/protect the Location were missing or insufficient. Inspections required Operator to comply with Rule 1002.f.(2)C.</p> <p>It was observed in this inspection that stormwater and erosion control measures remain missing or insufficient on the Location in accordance with Rule 1002.f.(2)C and corrective actions; BMPs to stabilize and protect the slopes of the Location remain missing or insufficient; sediment trap not constructed in accordance with good engineering practices and does not appear to be sufficient in size; scouring/degradation becoming evident around riprap at outlet; slope drains have not been constructed with an appropriate outlet in accordance with good engineering practices; inlet for slope drain on the southeastern end of the location not observed, inlet appears to have been covered/filled with sediment.</p> <p>This corrective action has not been addressed and remains applicable.</p>	trujilloam	05/25/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402700103	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5440155">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5440155</a>
696202715	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5440149">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5440149</a>