

**TEP ROCKY MOUNTAIN LLC
MOBIL-66S95W 33NWSE
Location # 323824**



TEP ROCKY MOUNTAIN LLC
MOBIL-66S95W 33NWSE
Location # 323824



**TEP ROCKY MOUNTAIN LLC
MOBIL-66S95W 33NWSE
Location # 323824**



Half inch line from GV W 2-33 to heated separator.



Line above ground with no protection from traffic.

**TEP ROCKY MOUNTAIN LLC
MOBIL-66S95W 33NWSE
Location # 323824**



Line above ground with no protection from traffic.



Half inch line from GV W 2-33 to heated separator.

**TEP ROCKY MOUNTAIN LLC
MOBIL-66S95W 33NWSE
Location # 323824**



Fencing damaged.



Fencing down.

TEP ROCKY MOUNTAIN LLC
MOBIL-66S95W 33NWSE
Location # 323824

