

FORM
6Rev
11/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

402650457

Date Received:

04/06/2021

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 69175

Contact Name: Valerie Danson

Name of Operator: PDC ENERGY INC

Phone: (970) 506-9272

Address: 1775 SHERMAN STREET - STE 3000

Fax:

City: DENVER State: CO Zip: 80203

Email: valerie.danson@pdce.com

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

Type of Well Abandonment Report: ☐ Notice of Intent to Abandon ☒ Subsequent Report of Abandonment

API Number 05-123-15573-00

Well Name: AGRICULTURAL PROD INC

Well Number: 11-7F

Location: QtrQtr: SWNE Section: 11 Township: 4N Range: 66W Meridian: 6

County: WELD Federal, Indian or State Lease Number: 66798

Field Name: WATTENBERG Field Number: 90750

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.328760 Longitude: -104.741500

GPS Data: GPS Quality Value: 2.0 Type of GPS Quality Value: Date of Measurement: 07/06/2006

Reason for Abandonment: ☐ Dry ☐ Production Sub-economic ☐ Mechanical Problems☐ OtherCasing to be pulled: ☐ Yes ☐ No Estimated Depth:Fish in Hole: ☐ Yes ☐ No If yes, explain details belowWellbore has Uncemented Casing leaks: ☐ Yes ☐ No If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
NIOBRARA-CODELL	6879	7210	02/09/2021	B PLUG CEMENT TOP	6829

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J55	24	0	505	360	505	0	VISU
1ST	7+7/8	4+1/2	J55	11.6	7295	7295	300	7295	5370	CBL
S.C. 1.1						4540	250	4540	3840	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 6829 with 2 sacks cmt on top. CIBP #2: Depth 4092 with 2 sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 100 sks cmt from 2560 ft. to 2300 ft. Plug Type: STUB PLUG Plug Tagged: ☐
Set 100 sks cmt from 1480 ft. to 1260 ft. Plug Type: OPEN HOLE Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 381 sacks half in. half out surface casing from 710 ft. to 0 ft. Plug Tagged: ☒

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: 2500 ft. of 4+1/2 inch casing

Surface Plug Setting Date: 02/10/2021 Cut and Cap Date: 02/16/2021 Number of Days from Setting Surface Plug to Capping or Sealing the Well: 6

*Wireline Contractor: NexTier Cementing Services

*Cementing Contractor: Rocky Mtn Wireline Services

Type of Cement and Additives Used: Class G 15.8 PPG Cement

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

Agricultural Prod Inc 11-7F (05-123-15573)/Plugging Procedure

Producing Formation: Niobrara/Codell: 6879'-7085'

Upper Pierre Aquifer: 380'-1360'

TD: 7311' PBTD: 7247' (3/5/2009)

Surface Casing: 8 5/8" 24# @ 505' w/ 360 sxs cmt

Production Casing: 4 1/2" 11.6# @ 7295' w/ 550 sxs cmt (TOC @ 3840' - CBL)

Procedure:

1. MIRU pulling unit. Pull 2 3/8" tubing.
2. RU wireline company.
3. TIH with CIBP. Set BP at 6829'. Top with 2 sxs 15.8#/gal CI G cement. (Top of Nio perms @ 6879')
4. TIH with CIBP. Set BP at 4092'. Top with 2 sxs 15.8#/gal CI G cement. (Top of Sussex @ 4142')
5. Ran a Strip Log from 2500' to Surface (for casing cut verification, log not kept).
6. TIH with casing cutter. Cut 4 1/2" casing @ 2500'. Pull cut casing.
7. TIH with tubing to 2560'. RU cementing company. Mix and pump 100 sxs 15.8#/gal CI G cement down tubing. (Stub plug from 2550'-2300') TOC at 2300'.
8. Wait a sufficient time to confirm static conditions. If at any time after placing this plug there is evidence of pressure or fluid migration, contact engineering before continuing operations
9. TIH with tubing to 1480'. Mix and pump 100 sxs 15.8#/gal CI G cement down tubing. (Pierre coverage from 1460'-1260') TOC at 1260'.
10. Pick up tubing to 710'. Mix and pump 381 sxs 15.8#/gal CI G cement down tubing. Cement circulate to surface.
11. Cut surface casing 6' below ground level and weld on cap.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: Valerie Danson

Title: Reg Tech

Date: 4/6/2021

Email: valerie.danson@pdce.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Jacobson, Eric

Date: 6/28/2021

CONDITIONS OF APPROVAL, IF ANY:**Condition of Approval****COA Type****Description**

0 COA

Attachment List**Att Doc Num****Name**

402650457	FORM 6 SUBSEQUENT SUBMITTED
402650485	CEMENT JOB SUMMARY
402650487	OTHER
402650488	OPERATIONS SUMMARY
402650489	WELLBORE DIAGRAM

Total Attach: 5 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)