

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/22/2021

Submitted Date:

06/28/2021

Document Number:

697601402

FIELD INSPECTION FORMLoc ID 476325 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Knop, Max	303-825-4822	MKnop@kpk.com	
Inspections, KPK		cogcc@kpk.com	All KPK Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478861	SPILL OR RELEASE	CL	06/09/2021		-	Premium Turkey Farm PW Vault	EI

General Comment:

Environmental inspection of spill 478861 and associated site investigation and remediation project 16538.

Past corrective actions still to be completed unless acknowledged as completed with FIRRs.

No Operator staff or contractors on site at time of inspection.

inadequate fencing around excavation at time of inspection.
excavation width, length and depth approximate
37 x 49 x 15 feet

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 200

Comment: Site had open excavation at site of former buried concrete vault produced water vessel without effective or adequate means of excluding entry of people, livestock or wildlife at time of inspection. Open excavation was part of site investigation and remediation project 14115 which remains open and is documented in attached photo.

Corrective Action: maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety and welfare and the environment as required by rule 913.b(5)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended. The site was not attended at the time of the inspection.

Date: 06/29/2021

Reportable: _____

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697601403	fencing extends over excavation edge and could not prevent access at bottom	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5465764