

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/22/2021

Submitted Date:

06/28/2021

Document Number:

697601404

FIELD INSPECTION FORM

Loc ID 317868 Inspector Name: GINTAUTAS, PETER On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 7 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Revas, Robbie		robbie.revas@state.co.us	
Knop, Max	303-825-4822	MKnop@kpk.com	
Inspections, KPK		cogcc@kpk.com	All KPK Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448083	TANK BATTERY	AC	10/17/2016		-	SIDNEY STREAR 1,2,3,4,5, 6 BATTERY	EI

General Comment:

[Environmental inspection of battery 448083 as partial followup to previous inspection](#)
[No removal of stained soils was completed at time of inspection as shown in attached photos.](#)

[equipment as in previous inspection 699303933](#)

[Any corrective actions from previous inspections that have not been addressed are still applicable](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	weeds as in photo attached		
Corrective Action:	Comply with Rule 606		Date: <u>07/05/2021</u>

Overall Good:

Spills:			
Type	Area	Volume	
Crude Oil	Tank		
Comment:	hole in crude tank with audible hissing		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. leak at crude tank must be addressed immediately and stopped		Date: <u>06/29/2021</u>
Crude Oil			
Comment:	several areas including PW buried vault and Emissions control device and spearator housing		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a by removing stained soils		Date: <u>07/31/2021</u>

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	BV CONCRETE		40.117989,-104.865990
Comment:	stained soils near concrete vault indicate spill of produced water from vault.				
Corrective Action:	Investigate soils around produced water vault including soil sampling and analysis for Table 915-1 as part of investigation of possible reportable spill, if reportable, form 19 must be submitted within 72 hours of determination.				Date: <u>07/01/2021</u>

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:	earthen berm shared with crude tanks			

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 448083 Type: TANK API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697601405	separator housing leak	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5465962
697601406	leak at crude tank base	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5465963
697601407	crude tank base	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5465964
697601408	crude soaked soils near crude tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5465965
697601409	crude stained soils near PW PBV	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5465966
697601410	weeds at crude tank berm	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5465967
697601411	crude stained soils at ECD	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5465968