

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402729985

Date Received:

06/25/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96155

Name of Operator: WHITING OIL & GAS CORPORATION

Address: 1700 LINCOLN STREET SUITE 4700

City: DENVER State: CO Zip: 80290

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Heil, John

john.heil@state.co.us

Kellerby, Shaun

shaun.kellerby@state.co.us

CO, Western

303-876-7091

whitingwesternco@whiting.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 701101608

Inspection Date: 06/16/2021

FIR Submit Date: 06/17/2021

FIR Status: _____

Inspected Operator Information:

Company Name: WHITING OIL & GAS CORPORATION

Company Number: 96155

Address: 1700 LINCOLN STREET SUITE 4700

City: DENVER State: CO Zip: 80290

LOCATION - Location ID: 315155

Location Name: HILL-61N101W Number: 6SEnw County: _____

Qtrqr: SEnw Sec: 6 Twp: 1N Range: 101W Meridian: 6

Latitude: 40.086770 Longitude: -108.774460

FACILITY - API Number: 05-103- -00 Facility ID: 315155

Facility Name: HILL-61N101W Number: 6SEnw

Qtrqr: SEnw Sec: 6 Twp: 1N Range: 101W Meridian: 6

Latitude: 40.086770 Longitude: -108.774460

CORRECTIVE ACTIONS:

2 ☒ CA# 151963

Corrective Action: Comply with Rule 606

Date: 06/26/2021

Response: CA COMPLETED

Date of Completion: 06/24/2021

Operator
Comment:

Weeds on the site have been resolved in accordance with Rule 606. See the attached photographs.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 151964

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 07/03/2021

Response: CA COMPLETED

Date of Completion: 06/24/2021

Operator
Comment: The chemical tank with damaged secondary container at the well was removed from the site. The damaged location berm and subsidence of ground at the line marker were resolved in accordance with Rule 1002.f.(2)C. See the attached photographs.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Bryce Maifeld

Signed: _____

Title: Regulatory Specialist

Date: 6/25/2021 8:38:35 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402729985	FIR RESOLUTION SUBMITTED
402729989	Photographs

Total Attach: 2 Files