

Location

Lease Road:			
Type	Access		
comment:	Location is not accessible during normal business hours. KP Kauffman lock is out of the sequence and cannot open gate.		
Corrective Action:	Provide key, combinations, or alternate method of access to comply with rule 204.	Date:	07/01/2021

Overall Good:

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 95%;" type="text"/>

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 95%;" type="text"/>

Flaring:

Type			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 95%;" type="text"/>

Inspected Facilities

Facility ID: 239993 Type: WELL API Number: 123-07781 Status: PR Insp. Status: PR

BradenHead

Date of Last Brhd Test: 09/28/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 6/29/2021 at approximately 1300 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at an KP Kauffman location: 1415 Corp Gas Unit B1 at API #05 -123-07781 in Weld County Colorado. While there, I observed a Locked gate. During this inspection the following possible compliance issues were observed: 204 Access: Location is not accessible during normal business hours. CA date 7-1-2021 See attached photos. Location: dry, Weather: clear. At 1305 hrs. I spoke with Stephanie with KP Kauffman field office and was told that she would has the lease operator go out and get the lock back in the sequence. At 1330 hrs I spoke with Manny Silva and was told that he would get in touch with the KP Kauffman Land Dept. and reach out to the land owner to get the lock back in sequence. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	06/30/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402735114	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5468697