

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/20/2021

Submitted Date:

07/29/2021

Document Number:

689806093**FIELD INSPECTION FORM**Loc ID 313026 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 3975Name of Operator: ARGALI EXPLORATION COMPANYAddress: PO BOX 416City: RANGELY State: CO Zip: 81648**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
General, Contact		argaliexplorationcompany@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223384	WELL	SI	01/01/2020	GW	081-06748	GRYNBERG STATE 3-36	SI

**General Comment:**

Routine FIU inspection. Form 9 to transfer from Mustang to Argali approved 10/6/2020 document number 402424253. Compliance issues observed:  
 signs not updated to current operator  
 no bradenhead access apparent

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Wellhead sign knocked over. Sign inaccurate.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	08/30/2021

**Emergency Contact Number:**

Comment:	No emergency contact for current operator.		
Corrective Action:	Install sign to comply with Rule 605.	Date:	08/30/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	#		
Comment:	Bradenhead inaccessible or not visible.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)	Date:	08/09/2021
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	223384	Type:	WELL	API Number:	081-06748	Status:	SI	Insp. Status:	SI
<div>Idle Well</div> <div>Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: </div> <div>Comment: </div> <div>Corrective Action: Date: </div>									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No stormwater BMPs observed. No apparent soil migration; erosion or soil movement.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689806094	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5492271">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5492271</a>