



Dallas 44-13



Installed appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).