

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/12/2021

Submitted Date:

08/02/2021

Document Number:

700200040**FIELD INSPECTION FORM**Loc ID 444819 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10542Name of Operator: CUB CREEK ENERGYAddress: 200 PLAZA DRIVE SUITE 100City: HIGHLANDS State: CO Zip: 80129**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
,		dan.berberick@cub-creek.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444820	WELL	PR	09/01/2020	OW	123-42769	Litzenberger 21	SI
444821	WELL	PR	09/01/2020	OW	123-42770	Litzenberger 10	SI
444822	WELL	PR	06/15/2018	OW	123-42771	Litzenberger 12	SI
444823	WELL	PR	09/01/2020	OW	123-42772	Litzenberger 13	SI
444824	WELL	PR	09/01/2020	OW	123-42773	Litzenberger 9	SI

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

# 5

Comment: 5 horizontal separators were damaged by fire/stained soil around separators

Corrective Action: Repair and inspect all equipment prior to operating/clean and remove stained soil

Date: 01/12/2022

**Venting:**

Yes/No

NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 444820	Type: WELL	API Number: 123-42769	Status: PR	Insp. Status: SI
Facility ID: 444821	Type: WELL	API Number: 123-42770	Status: PR	Insp. Status: SI
Facility ID: 444822	Type: WELL	API Number: 123-42771	Status: PR	Insp. Status: SI
Facility ID: 444823	Type: WELL	API Number: 123-42772	Status: PR	Insp. Status: SI
Facility ID: 444824	Type: WELL	API Number: 123-42773	Status: PR	Insp. Status: SI

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 07-12-2021 at approximately 1000hrs, I, conducted an inspection of Cub Creek Litzenberger location in reference to a fire which had occurred at location Location # 44819 in Weld County Colorado.</p> <p>The purpose of this inspection was to determine the extent of the damaged caused by the fire at the location. When I arrived I observed the separators on the south end of the location had been damaged by the fire. I observed 5 to six of the horizontal heated separators had been damaged by the fire. I also observed the soil around these separators appeared to have stained soil.</p> <p>Corrective actions of repairing and inspecting equipment and cleaning up stained soil prior to operations of equipment were issued for this inspection.</p> <p>Drone images were taken of location and are attached to this inspection.</p> <p>At the time of the inspection no personnel from Cub Creek where on location to interview.</p> <p>All corrective action from previous and further inspection must be completed to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	gomezj	08/02/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700200041	Fire damage	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5496007">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5496007</a>