

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402777257

Date Received:  
08/11/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 76840  
Name of Operator: SCHNEIDER ENERGY SERVICES INC  
Address: P O BOX 889  
City: FORT MORGAN State: CO Zip: 80701  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Axelson, John</u>		<u>john.axelson@state.co.us</u>
<u>Medina, Justin</u>		<u>justin.medina@state.co.us</u>
<u>Gomez, Jason</u>		<u>jason.gomez@state.co.us</u>
<u>SCHNEIDE, JEFF R</u>	<u>970-867-9437</u>	<u>jeff@schneiderenergy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696900159  
Inspection Date: 05/10/2021 FIR Submit Date: 05/25/2021 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: SCHNEIDER ENERGY SERVICES INC Company Number: 76840  
Address: P O BOX 889  
City: FORT MORGAN State: CO Zip: 80701

LOCATION - Location ID: 319636

Location Name: COORDES-61S57W Number: 7NESW County: \_\_\_\_\_  
Qtrqtr: NESW Sec: 7 Twp: 1S Range: 57W Meridian: 6  
Latitude: 39.975125 Longitude: -103.813666

FACILITY - API Number: 05-001- -00 Facility ID: 479951

Facility Name: Cordes 3 Tank Battery Number: \_\_\_\_\_  
Qtrqtr: NESW Sec: 7 Twp: 1S Range: 57W Meridian: 6  
Latitude: 39.975125 Longitude: -103.813666

CORRECTIVE ACTIONS:

1 CA# 151360

Corrective Action: Rebuild secondary containment per Rule 603.o

Date: 08/11/2021

Response: CA COMPLETED

Date of Completion: 08/11/2021

The assessment at the site is on-going; the tank battery will be rebuilt with steel containment per Rule 603.o. once we close out all assessment and remedial activities.

Operator  
Comment:

COGCC Decision:

COGCC  
Representative:

2 CA# 151361

Corrective Action: Spill clean-up will include vegetation impact at the tank battery and along the spill flow path. All top soil removed as part of the remediation actions must be replaced with equal quality top soil and properly reclaimed per Rule 1003.

Date: 08/11/2021

Response: CA COMPLETED

Date of Completion: 08/11/2021

Operator  
Comment:

Spill-clean up is progressing and preparing Form 19 supplemental report with all required analytical, waste manifest and pictures. Inert Fill application has been approved by Adams county. Once confirmation samples and report are complete SES will replace required topsoil per Rule 1003.

COGCC Decision:

COGCC  
Representative:

3 CA# 151362

Corrective Action: Proper reclamation is required under Rule 1003 to address the erosion and lack of vegetation.

Date: 08/11/2021

Response: CA COMPLETED

Date of Completion: 08/11/2021

Operator  
Comment:

Proper reclamation per Rule 1003 will commence to address the erosion and lack of vegetation in the areas of the spill once all assessment and remedial activities are complete

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jeff Schneider

Signed:

Title: President

Date: 8/11/2021 3:52:33 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files