

OIL AND GAS CONSERVATION COMMISSION DEPARTMENT OF NATURAL RESOURCES OF THE STATE OF COLORADO

OCT 7 1971



00817838

File in duplicate for Patented and Federal lands.
File in triplicate for State lands.

COLO. OIL & GAS CONS. COMM.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO.
2. NAME OF OPERATOR The Bovaird Supply Company 308 235-4638		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 1032 Kimball, Nebraska 69145		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <i>Formerly art Guida #1 Green</i>		8. FARM OR LEASE NAME Green
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		10. FIELD AND POOL, OR WILDCAT MT HOPE EAST
		11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA 20-9N-53W
		12. COUNTY Logan
		13. STATE COLO

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☒MULTIPLE COMPLETE ☐ABANDON ☐CHANGE PLANS ☐**Plug** ☒

SUBSEQUENT REPORT OF:


WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work **Soon As Possible**

**Dump Sand Across Perf. & 5 Sacks Cement Plug -- 9# Mud Between Pugs--
10 Across Surface Casing Shoe -- 10 Sacks At Top -- Weld Plate on Top
Of Surface.**

PERFORATION: **J-1 Sand 5032-34' & 5048-52'**TD -- **5120**PBTD -- **5090**

18. I hereby certify that the foregoing is true and correct

SIGNED **J. A. Peterson**TITLE **Store Manager**DATE **10-4-71**

(This space for Federal or State office use)

APPROVED BY **[Signature]**
CONDITIONS OF APPROVAL, IF ANY:TITLE **DIRECTOR**
O & G CONS. COMM.DATE **OCT 8 1971**