

TEP
RMV 55-20
Location # 335251



location



location

TEP
RMV 55-20
Location # 335251



location



location/lack of separator bath labels

TEP
RMV 55-20
Location # 335251



Lack of stabilization/compaction



Lack of stabilization/compaction

TEP
RMV 55-20
Location # 335251



Lack of stabilization/compaction



Lack of stabilization/compaction

TEP
RMV 55-20
Location # 335251



Load out lines missing bull plugs/caps



Load out lines missing bull plugs/caps