

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/28/2021

Submitted Date:

08/05/2021

Document Number:

700900619

FIELD INSPECTION FORM

Loc ID 320067 Inspector Name: Finkenbinder, Chane On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10695
Name of Operator: BEHRENS RESOURCES INC
Address: PO BOX 188
City: DEER TRAIL State: CO Zip: 80135

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Behrens, Vic	303-810-6382	behrens@netecin.net	Inspections

General Comment:

Location

Lease Road:			
	Type	Access	
	comment:	Access road unpassable	
Corrective Action:	Location is within a designated setback location, maintain and repair access roads per Rule 604.c.(2)S. Corrective Action Date 8/31/2021. See attached photo # 1 & 2		Date: 08/31/2021

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday July 28, 2021 at approximately 11:00am. I, Inspector Chane Finkenbinder, conducted an on-site inspection at Farm Ranch Exploration 3 – Behrens Resources LLC, at API # 001-07888 in Adams County Colorado.</p> <p>While there, I observed a shut in well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Access roads. Location is within a designated setback location, maintain and repair access roads per Rule 604.c.(2)S. Corrective Action Date 8/31/2021. See attached photo # 1 & 2</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	finkenbc	08/05/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700900620	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5513247