

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/24/2021

Submitted Date:

08/26/2021

Document Number:

696303546

FIELD INSPECTION FORMLoc ID 327641 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 70385

Name of Operator: SMITH ENERGY CORP

Address: 12706 SHILOH RD

City: GREELEY State: CO Zip: 80631

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Chris	(970) 330-7034	smithenergy@live.com	
,		dnr_cogccengineering@state.co.us	
Kraich, Adam		adam.kraich@state.co.us	
Smith, Glenn	(970) 381-6253	gsmithten@what-wire.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247164	WELL	SI	06/01/2018	OW	123-14961	TAYLOR 15-2	SI

General Comment:

This is a Follow-Up to FIR 696302585 dated 10.22.2020

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:		
Type	WEEDS	
Comment:	Weeds remain at Pumping Unit, see photos. Same Corrective Action Date Applies	
Corrective Action:	Comply with Rule 606.c.	Date: 10/18/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 0		
Comment:	Appears NOT to be plumbed to surface		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)		Date: 09/06/2021
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

Venting:		
Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:		
Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 247164 Type: WELL API Number: 123-14961 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI - Shut-In since 06/01/2018. 2-Year MIT is due on 06/01/2020 per Rule 326.b. Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

Corrective Action: Well must be either:Date: 01/22/2021

1) Per COGCC Rule 326.b.(1) a successful mechanical integrity test shall be performed on each shut-in well within two (2) years of the initial shut-in date or

2) Be properly plugged and abandoned. Shut-in and temporarily abandoned wells must be properly reported on COGCC Form 7, Operator's Monthly Production Report.

BradenHeadDate of Last Brhd Test: _____ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: NO Annual Test on Record.Date: 09/27/2021

Corrective Action:

Comply with Rule 420

The Operator will submit results of Bradenhead tests to the Director within 10 days of completing the test either by filing a Form 17, Bradenhead Test Report or by another method approved by the Director or Commission. The Operator will include a wellbore diagram if not previously submitted or if the wellbore configuration has changed. The Director may request that the Operator collect samples for analysis of the Bradenhead gas and liquid along with production gas. The Operator will submit the results of any gas and liquid analysis collected using a Form 43.

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On Tuesday 08/17/2021 at approximately 13:13. I, Inspector, Erica Petrie, conducted a Follow-Up On-Site Inspection at SMITH ENERGY CORP, Taylor 15-2, Location ID: 327641 in Weld County, Colorado</p> <p>While there, I observed Production Observations</p> <p>Entire Well, Battery & Equipment is shut-down.</p> <p>Weed encroachment at Pumping Unit. See photos. Remove, manage, & control weeds at Pumping Unit. Comply with Rule 606.c. Corrective Action date: 10/18/2019.</p> <p>Well SI since 06.01.2018 no MIT on record. Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Produce well after performing successful Mechanical Integrity Test per Rule 326 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention. Corrective Action date: 01/22/2021.</p> <p>Bradenhead appears to NOT be plumbed. Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2). Corrective Action date 09/06/2021</p> <p>NO Current Annual Bradehead Test on File. Comply with Rule 420 The Operator will submit results of Bradenhead tests to the Director within 10 days of completing the test either by filing a Form 17, Bradenhead Test Report or by another method approved by the Director or Commission. The Operator will include a wellbore diagram if not previously submitted or if the wellbore configuration has changed. The Director may request that the Operator collect samples for analysis of the Bradenhead gas and liquid along with production gas. The Operator will submit the results of any gas and liquid analysis collected using a Form 43. Corrective Action Date 09.27.2021</p> <p>A follow up site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p>	petrie	08/26/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696303548	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5516442