

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/28/2021

Submitted Date:

08/05/2021

Document Number:

700900619**FIELD INSPECTION FORM**Loc ID 320067 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10695

Name of Operator: BEHRENS RESOURCES INC

Address: PO BOX 188

City: DEER TRAIL State: CO Zip: 80135

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Behrens, Vic	303-810-6382	behrens@netecin.net	Inspections

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Access road unpassable		
Corrective Action	Location is within a designated setback location, maintain and repair access roads per Rule 604.c.(2)S. Corrective Action Date 8/31/2021. See attached photo # 1 & 2	Date:	08/31/2021

Overall Good: ☐

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday July 28, 2021 at approximately 11:00am. I, Inspector Chane Finkenbinder, conducted an on-site inspection at Farm Ranch Exploration 3 – Behrens Resources LLC, at API # 001-07888 in Adams County Colorado.</p> <p>While there, I observed a shut in well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Access roads. Location is within a designated setback location, maintain and repair access roads per Rule 604.c.(2)S. Corrective Action Date 8/31/2021. See attached photo # 1 & 2</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	finkenbc	08/05/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402789842	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5513254

700900620	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5513247
-----------	-------------------	---

