

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/07/2021

Submitted Date:

09/08/2021

Document Number:

689806328**FIELD INSPECTION FORM**Loc ID 442674 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 6720Name of Operator: ROBERT L BAYLESS PRODUCER LLCAddress: 621 17TH ST STE 2300City: DENVER State: CO Zip: 80293**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Helen		notices@rlbayless.com	<a href="#">All inspections</a>
		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442675	WELL	WO	09/10/2015	LO	081-07821	Foster State 1	TA

**General Comment:**

Routine FIU inspection. Compliance issues observed:  
 no bradenhead access apparent  
 no current MIT  
 no Form 4 for TA status  
 access road overgrown  
 sediment migrating onto location  
 sediment migrating off of location  
 cuttings stored on location and migrating around location

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access road overgrown.		
Corrective Action	Repair and maintain lease road to comply with rule 204.	Date:	10/08/2021

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Battery sign at entrance to location. No sign at wellhead.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	11/08/2021

Emergency Contact Number:

Comment: 505-326-2659

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Cuttings remain stored on location and are beginning to migrate around location.		
Corrective Action:	Comply with Rule 606.	Date:	10/08/2021
Type	OTHER		
Comment:	It appears location is being used as a staging/feeding area for livestock.		
Corrective Action:	Comply with Rule 606.	Date:	10/06/2021

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	442675	Type:	WELL	API Number:	081-07821	Status:	WO	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned      Reminder: _____									
<u>Comment:</u> Well has been TA since last MIT 10/2/2015 document number 400918550. No Form(s) 4 for TA status on file.									
Corrective Action: _____      Date: _____									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater BMPs have not been maintained. Sediment leaving location through collapse of fill on west side. Sediment migrating onto location and mixing with cuttings.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 09/15/2021

Pits: ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689806329	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5525924">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5525924</a>