

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/31/2021

Submitted Date:

09/03/2021

Document Number:

697601510

**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
GINTAUTAS, PETER 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Knop, Max	303-825-4822	MKnop@kpk.com	
Inspections, KPK		cogcc@kpk.com	All KPK Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
479834	SPILL OR RELEASE	CL	07/30/2021		-	Suckla Farms E #2 Flowline	EI

**General Comment:**

Steel panel fencing in place surrounding excavation. No Operator staff present at time of inspection

Ongoing Remediation project 19028 at now closed spill 479834.

Sorbent booms observed in main excavation in effort to minimize horizontal transport of crude oil in precipitation event are not in place near hydrocarbon liquids at time of inspection. This inspection entered to document conditions observed at time of inspection. Operator has indicated they removed observed hydrocarbon liquids prior to this inspection being submitted.

No barrier to prevent infiltration of crude oil and associated impacts to deeper soils and to shallow groundwater at site during precipitation or irrigation events.

Weeds noted in previous two inspection (07/21/2021 and 08/17/2021) have been removed from excavation area.

Inspected Facilities									
Facility ID:	479834	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI

--

**Environmental****Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: \_\_\_\_\_

Comment: attached photo to document presence of free hydrocarbon liquids/product flating on water at bottom of excavation for spill 479834.

Corrective Action: remove free liquids/product within 24 hour of notice.Email notice sent on 08/31/21 and acknowledged by Operator staff on same day.email attached.Control and contain spills/releases and clean up per Rule 912.a.

Date: 09/01/2021

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: Other \_\_\_\_\_

Comment: bottom of excavation

**Sample** Sample Type: SOIL GRAB

Time: 08/31/2021 07:44 (MM/dd/yyyy hh:mm) GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

BTX: \_\_\_\_\_ TPH: YES \_\_\_\_\_ Anion: \_\_\_\_\_ Captions: \_\_\_\_\_ General Chemistry: \_\_\_\_\_

Dissolved Methane: \_\_\_\_\_ Composition: \_\_\_\_\_ Stable Isotopes: \_\_\_\_\_ 8260: \_\_\_\_\_

8270: \_\_\_\_\_ RCRA Metals: \_\_\_\_\_ 910-Metals: YES \_\_\_\_\_ PAH: YES \_\_\_\_\_

Other: SIMPAH by 8270 and Table 915-1 metals by 6020

Comment: oily soil from bottom of excavation about 2 feet from liquid HC on water

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402802519	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5523893">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5523893</a>
697601511	free product on aqueous zone	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5523891">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5523891</a>
697601512	email notice of required actions 08/31/21 and response	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5523892">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5523892</a>