

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/03/2021

Submitted Date:

09/07/2021

Document Number:

690202042**FIELD INSPECTION FORM**Loc ID 308128 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 6295 GREENWOOD PLAZA BLVD #100City: GREENWOOD State: CO Zip: 8111-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mack, Ronald		rmack@ogrisop.com	
Thomsen, Dylan		timothy.thomsen@state.co.us	
Fitzgerald, Edie		efitzgerald@ogrisop.com	
ATWATER, BONNIE		batwater@ogrisop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262543	WELL	PR	07/01/2017	GW	071-07560	APACHE CANYON 10-16V	RI

General Comment:

This is a follow up of the previous stormwater management inspections; #690200711, #690201491.
The corrective action of the previous inspections have not been performed.
See attached photos and additional details within this report.

Location

Lease Road:			
Type	Access		
comment:	See stormwater section.		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	TRASH		
Comment:	There is insulation debris that needs to be cleaned up and removed.		
Corrective Action:	Comply with Rule 606. Remove debris.		Date: 09/17/2021

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is vehicle rutting and road degradation traveling to the location. There are areas where stormwater is not properly diverted causing stormwater to accumulate on the road. Areas of erosion along the road need to be repaired and properly stabilized. Culverts along the road need to be maintained. Previous corrective action has not been performed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C Date: 10/01/2020

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Change of Operator is listed as OGRIS OPERATING LLC.	CostaR	09/07/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402804141	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5525314
690202043	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5525308