

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/07/2021

Submitted Date:

09/08/2021

Document Number:

689806328**FIELD INSPECTION FORM**Loc ID 442674 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 6720Name of Operator: ROBERT L BAYLESS PRODUCER LLCAddress: 621 17TH ST STE 2300City: DENVER State: CO Zip: 80293**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
Trujillo, Helen		notices@rlbayless.com	All inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442675	WELL	WO	09/10/2015	LO	081-07821	Foster State 1	TA

General Comment:

Routine FIU inspection. Compliance issues observed:

- no bradenhead access apparent
- no current MIT
- no Form 4 for TA status
- access road overgrown
- sediment migrating onto location
- sediment migrating off of location
- cuttings stored on location and migrating around location

Location			
Lease Road:			
Type	Access		
comment:	Access road overgrown.		
Corrective Action	Repair and maintain lease road to comply with rule 204.		Date: 10/08/2021
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Battery sign at entrance to location. No sign at wellhead.		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: 11/08/2021
Emergency Contact Number:			
Comment:	505-326-2659		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	It appears location is being used as a staging/feeding area for livestock.		
Corrective Action:	Comply with Rule 606.		Date: 10/06/2021
Type	OTHER		
Comment:	Cuttings remain stored on location and are beginning to migrate around location.		
Corrective Action:	Comply with Rule 606.		Date: 10/08/2021
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected FacilitiesFacility ID: 442675 Type: WELL API Number: 081-07821 Status: WO Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Well has been TA since last MIT 10/2/2015 document number 400918550. No Form(s) 4 for TA status on file.

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		Stormwater BMPs have not been maintained. Sediment leaving location through collapse of fill on west side. Sediment migrating onto location and mixing with cuttings.				
Corrective Action:		Install or repair required BMPs per Rule 1002.f.(2)C				Date: 09/15/2021
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402804863	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5525931
689806329	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5525924