

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Lubricator is leaking. See attached photo.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: <u>10/11/2021</u>
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	Location #328416				
Corrective Action:				Date:	

Paint

Condition	<input type="text"/>		
Other (Content)	<input type="text"/>		

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date: <input style="width:100px;" type="text"/>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date: <input style="width:100px;" type="text"/>

Flaring:

Type		
Comment:		
Corrective Action:		Date: <input style="width:100px;" type="text"/>

Inspected Facilities

Facility ID: 248168 Type: WELL API Number: 123-15966 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/22/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass	Seeding	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 9/8/2021 at approximately 09:50 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Noble Energy Ehrlich 23-14 location #328417 in Weld County, Colorado. While there, I observed that the plunger lubricator had developed a leak. During this inspection the following possible compliance issues were observed: Rule 608.e. with a corrective action date of 10/11/2021. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p>	petersont	09/08/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402805261	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5526374
697004513	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5526366