



**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Overgrown vegetation on the lease road needs to be removed for good housekeeping. See attached photos		
Corrective Action	Comply with Rule 606 & Rule 603.I	Date:	09/17/2021

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	Adequate		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 296792 Type: WELL API Number: 123-26910 Status: SI Insp. Status: SI**Idle Well**Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 05/30/2020 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 6 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0Comment: No updated annual bradenhead test on file. Submit reports.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>  On Wednesday 9/8/21 at approximately 0921hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Guttersen D09-09 of Noble Energy, at Location ID # 310745 in Weld County, Colorado.  During this inspection the following possible compliance issues were observed:  Overgrown vegetation on the lease road needs to be removed for good housekeeping.  Comply with Rule 606 &amp; Rule 603.I. With a corrective action date of 9/17/21  See attached photos.  A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  This is a summary of inspection report.</p>	burnsa	09/08/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402805516	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5526604">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5526604</a>
699104399	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5526598">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5526598</a>