

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/15/2021

Submitted Date:

09/21/2021

Document Number:

694500369

FIELD INSPECTION FORMLoc ID 316764 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 6720

Name of Operator: ROBERT L BAYLESS PRODUCER LLC

Address: 621 17TH ST STE 2300

City: DENVER State: CO Zip: 80293

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
thomas, john	505-326-2659	jthomas@rlbayless.com	
Trujillo, Helen		htrujillo@rlbayless.com	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232726	WELL	PR	02/01/2021	OW	107-06140	DRY CREEK FEDERAL 1-14	EI

General Comment:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: FlareLined: NOPit ID: 480784Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment:

Pit is not currently in use, it is being closed. Pit ID was created by COGCC staff. At time of inspection, it was apparent that impact remains in soil after initial excavation. Groundwater appears to be shallow in the area.

Corrective Action:

within 21 days of receiving sample results of soil sampling, submit on a supplemental Form 27.

Date: 11/30/2021**Fencing:**Fencing Type: SafetyFencing Condition: InadequateComment:

fence was removed to allow work on pit

Corrective Action:

prevent wildlife from entering pit.

Date: **Netting:**Netting Type: Netting Condition: Comment:

no netting

Corrective Action: Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500370	photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5536766