





Flowline put back in service.





Crew dugout wooden containment and dirt fill around pit, installed guy line markers, cleaned up debris, placed piping back in service, disked, seeded and mulched location to correct erosion rills and re-establish vegetation around location.





















