



**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	location entrance is adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 414898 Type: WELL API Number: 123-30882 Status: PR Insp. Status: PR

**BradenHead**

Date of Last Brhd Test: 07/02/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE  
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Workover**

Comment: [Form 42 MIRU Doc # 402809996. Arrived on location, workover rig crew TOO H to set plugs, Ranger logging truck on standby waiting to set plugs.](#)

Corrective Action:

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On Thursday 9/23/2021 at approximately 1130 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Chevron/Noble location:</p> <p style="text-align: center;"><a href="#">HP Farms USX Y 17-6 at API #05-123-30882 in Weld County Colorado.</a></p> <p><a href="#">While there, I observed a workover operation, Form 42 MIRU Doc # 402809996. Arrived on location, workover rig crew TOO H to set plugs, Ranger logging truck on standby waiting to set plugs. Logging Truck RU and RIH with CIBP, Set at 7469 ft. with 2 sxs cement left on top.</a></p> <p><a href="#">During this inspection no compliance issues were observed: See attached photos.</a></p> <p><a href="#">Location: dry, Weather: clear.</a></p> <p><a href="#">I spoke with Omar Fabela Chevron/Noble Wellsite Supervisor about current operations, Plug to be set at 7469 ft.</a></p> <p><a href="#">No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</a></p> <p><a href="#">This is a summary of inspection report.</a></p>	revasr	09/23/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699304320	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5539352">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5539352</a>