



McDonald 33-31 and TR

Lowered fluid level so at least two feet of freeboard exists per Rule 902.b.