

FORM

6

Rev
11/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

402673247

Date Received:

04/30/2021

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 100322

Contact Name: Kevin Monaghan

Name of Operator: NOBLE ENERGY INC

Phone: (970) 3812990

Address: 1001 NOBLE ENERGY WAY

Fax:

City: HOUSTON State: TX Zip: 77070

Email: kevin.monaghan@nblenergy.com

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

Type of Well Abandonment Report:



Notice of Intent to Abandon



Subsequent Report of Abandonment

API Number 05-123-30781-00

Well Name: DERR

Well Number: 17-4

Location: QtrQtr: SENE Section: 4 Township: 5N Range: 65W Meridian: 6

County: WELD

Federal, Indian or State Lease Number:

Field Name: GREELEY

Field Number: 32760

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.431338

Longitude: -104.663357

GPS Data: GPS Quality Value: 1.8 Type of GPS Quality Value: Date of Measurement: 06/14/2010

Reason for Abandonment:



Dry



Production Sub-economic



Mechanical Problems

☐ Other

Casing to be pulled:



Yes



No

Estimated Depth:

Fish in Hole:



Yes



No

If yes, explain details below

Wellbore has Uncemented Casing leaks:



Yes



No

If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7030	7046	02/04/2021	B PLUG CEMENT TOP	6676
NIOBRARA	6726	6930	02/04/2021	B PLUG CEMENT TOP	6676

Total: 2 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J55	24		878	550	878	0	VISU
1ST	7+7/8	4+1/2	I80	11.6		7199	810	7199	1380	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 6676 with 2 sacks cmt on top. CIBP #2: Depth 2000 with 2 sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 116 sks cmt from 1330 ft. to 1141 ft. Plug Type: OPEN HOLE Plug Tagged: ☒
Set 218 sks cmt from 725 ft. to 0 ft. Plug Type: CASING Plug Tagged: ☒
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 133 sacks half in. half out surface casing from 1141 ft. to 725 ft. Plug Tagged: ☒

Set 3 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: 1330 ft. of 4+1/2 inch casing

Surface Plug Setting Date: 02/08/2021 Cut and Cap Date: 03/31/2021 Number of Days from Setting Surface Plug to Capping or Sealing the Well: 51

*Wireline Contractor: SPN

*Cementing Contractor: SPN

Type of Cement and Additives Used: Class G Neat

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☒ No

Technical Detail/Comments:

Procedure Modification Email attached.

CSG Cut/Pull @ 1330'

3 sxs top off, no cmt ticket available for top off

Form 17 DocNum: 402611388

Form 27 DocNum: 402595920

Form 42 DocNum: 402585097

Form 44 DocNum: Flowline will be abandoned.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Lauren Hoff

Title: HSE Reg Affairs Coord Date: 4/30/2021 Email: DenverRegulatory@nblenergy.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Jacobson, Eric Date: 10/11/2021

CONDITIONS OF APPROVAL, IF ANY:

Condition of Approval

COA Type**Description**

0 COA	

Attachment List

Att Doc Num**Name**

402673247	FORM 6 SUBSEQUENT SUBMITTED
402673281	CEMENT JOB SUMMARY
402673283	OPERATIONS SUMMARY
402673285	OTHER
402673286	WELLBORE DIAGRAM
402673287	WIRELINE JOB SUMMARY

Total Attach: 6 Files

General Comments

User Group**Comment****Comment Date**

Engineer	Form 44 Doc# 402698687	10/11/2021
----------	------------------------	------------

Total: 1 comment(s)