

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type OTHER

Comment: [Spill that was discovered from Inspection Document # 699502721 has not been addressed since discovery on 4/29/21. Free standing fluids were addressed but flowline in questions has not been repaired and area of effect has not been addressed by KPK.](#)

Corrective Action: [Comply with 912 a](#)

Date: 06/11/2021

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: [Yellow fabricated fencing](#)

Corrective Action:

Date:

Equipment:

corrective date

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment # 1

Comment: [Automation](#)

Corrective Action:

Date:

Type: Bradenhead # 1

Comment: [Plumbe to surface](#)

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 242493 Type: WELL API Number: 123-10284 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 05/06/2020 Annual Brhd Completed? No
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: Annual bradenhead test is not current. Contact COGCC engineering. 10/15/2021
 Corrective Action: Comply with COGCC annual bradenhead testing rules Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 10/5/21 at approximately 1300 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- George R Norden Unit 1 Company Name- KPK API- 05-001-10284 In Weld County Colorado. While there, I observed PR well This is a follow up inspection from document # 699502721 Corrective Actions are Delinquent During this inspection the following possible compliance issues were observed: Spill that was discovered from Inspection Document # 699502721 has not been addressed since discovery on 4/29/21. Free standing fluids were addressed however flowline in questions has not been repaired and area of effect has not been addressed by KPK. Comply with 912 a 4/29/21 Annual bradenhead test is not current. Contact COGCC engineering. Comply with COGCC annual bradenhead testing rules 10/15/21 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	10/05/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402832334	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5547897
699503231	Inspection Pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5547895