

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/12/2021

Submitted Date:

10/13/2021

Document Number:

689806539

FIELD INSPECTION FORM
 Loc ID 312960 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 6720

Name of Operator: ROBERT L BAYLESS PRODUCER LLC

Address: 621 17TH ST STE 2300

City: DENVER State: CO Zip: 80293

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
Trujillo, Helen		notices@rlbayless.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223036	WELL	PR	11/01/2020	GW	081-06398	COTTONWOOD GULCH FEDERAL C-1	PR

General Comment:
 Routine FIU inspection. Compliance issues observed:
 no bradenhead access apparent
 animal burrows compromising tank berm

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	#		
Comment:	Bradenhead inaccessible or not visible.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)	Date:	10/25/2021

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST		,
Comment:					

Corrective Action:		Date:	
Paint			
Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			
Berms			
Type	Capacity	Permeability (Wall)	Maintenance
Earth	Inadequate		Inadequate
Comment:		Animal burrows compromising berm.	
Corrective Action:		Repair or install berms or other secondary containment devices.	
		Date: 11/15/2021	
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities				
Facility ID: 223036	Type: WELL	API Number: 081-06398	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No stormwater BMPs observed. No apparent soil migration; erosion or soil movement.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689806540	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5554595