

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/11/2021

Submitted Date:

10/11/2021

Document Number:

693505515

FIELD INSPECTION FORM

Loc ID 320511 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,	303-825-4822	cogcc@kpk.com	All Inspections
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272178	WELL	SI	03/01/2021	GW	001-09507	STANDLEY 2-2	SI
272179	WELL	SI	02/01/2021	GW	001-09506	STANDLEY 1-2	SI

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 272178 Type: WELL API Number: 001-09507 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI Form 42 MIRU Doc # 402834172 on file with the COGCC

Corrective Action: Date:

Facility ID: 272179 Type: WELL API Number: 001-09506 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI No form 42 MIRU on file with the COGCC. Crew is onsite to remove Bridge Plug. Notice to move-in, rig-up was not given in required timeframe prior to commencement of move-in, rig-up.

Corrective Action: Submit required notice as per Rule 405.e. Date: 10/13/2021

Workover

Comment: KPK Rig. Spoke with forman on site he stated they were removing bridge plug. At time of inspection crew was actively rigging up.

Corrective Action: Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday October 11, 2021 at approximately 10:13AM, I, Inspector Randy Silver, conducted an on-site inspection due to form 42 notice. Location: Standley 2-2 and 1-2 Operator: KP Kauffman API#: 001-09506 County: Adams While there, I observed Work over operations. During this inspection the following possible compliance issues were observed: Reporting: Rule 405 e Corrective action date of 10-13-21 Weather conditions: clear and dry I spoke with KPK forman onsite who stated they were removing bridge plugs on both well. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	10/11/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402837160	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5551412
693505516	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5551410