

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402857157

Date Received:  
10/29/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10112  
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
.		<u>regulatory@foundationenergy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696303705  
Inspection Date: 10/21/2021 FIR Submit Date: 10/21/2021 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC Company Number: 10112  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 332405

Location Name: BABB-66N61W Number: 14SESW County: WELD  
Qtrqr: SESW Sec: 14 Twp: 6N Range: 61W Meridian: 6  
Latitude: 40.482740 Longitude: -104.178120

FACILITY - API Number: 05-123- -00 Facility ID: 272629

Facility Name: BABB Number: 14-14  
Qtrqr: SESW Sec: 14 Twp: 6N Range: 61W Meridian: 6  
Latitude: 40.482740 Longitude: -104.178120

CORRECTIVE ACTIONS:

1 CA# 157040

Corrective Action: Comply with Rule 606 Date: 10/29/2021

Response: CA COMPLETED Date of Completion: 10/29/2021

Operator Comment: Corrective action completed; see attached photos.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 157041

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.  
For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

Date: 11/29/2021

Response: CA COMPLETED

Date of Completion: 10/29/2021

Operator  
Comment:

Stained soil at wellhead has been disposed; see attached photo.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**3** CA# 157042

Corrective Action: Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.

Date: 11/22/2021

Response: CA COMPLETED

Date of Completion: 10/29/2021

Operator  
Comment:

Finer mesh netting was placed over the original pit netting; see attached photo.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions have been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Afton Iiams

Signed: \_\_\_\_\_

Title: HSE/Regulatory Technician

Date: 10/29/2021 9:16:53 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402857227	Location Photos
-----------	-----------------

Total Attach: 1 Files