

Location

Lease Road:			
	Type	Access	
	comment:	Access road to well sight has been planted over and not maintained	
Corrective Action:	Access roads. Location is within a designated setback location, maintain and repair access roads per Rule 604.c.(2)S. Corrective Action Date 11/18/2021. See attached photo # 1		Date: 11/18/2021

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 100%;" type="text"/>
Corrective Action:	<input style="width: 100%;" type="text"/>
	Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:			Date:

Flaring:			
Type			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:			Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday October 13, 2021 at approximately 11:00am. I, Inspector Chane Finkenbinder, conducted an on-site inspection at Farm Ranch Exploration 3 – Behrens Resources LLC, at API # 001-07888 in Adams County Colorado. While there, I observed a shut in well. During this inspection the following possible compliance issues were observed: No actions taken from doc# 700900619. Access road to Pump Jack has been planted over and not maintained. Location is within a designated setback location, maintain and repair access roads per Rule 604.c.(2)S. Corrective Action Date 11/18/2021. See attached photo # 1 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	10/29/2021

Attached Documents
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700900819	inspection photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5568686