

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/30/2021

Submitted Date:

10/15/2021

Document Number:

700900794

FIELD INSPECTION FORM

Loc ID 319973 Inspector Name: Finkenbinder, Chane On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 31257
Name of Operator: FRITZLER RESOURCES INC
Address: P O BOX 114
City: FORT MORGAN State: CO Zip: 80701

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	All Inspections

General Comment:

Location

Lease Road:			
	Type Access		
comment:	Access roads not accessible or maintained to get to well.		
Corrective Action:	Location is within a designated setback location, maintain and repair access roads per Rule 204. Corrective Action Date 11/12/2021. See attached photo #1.	Date:	11/12/2021

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday September 30, 2021. at approximately 12:00pm. I, Inspector Chane Finkenbinder, conducted an on-site inspection at Simpson A12, Fritzier Oil, at API #001-07472 in Adams County Colorado. While there, I observed a producing well. During this inspection the following possible compliance issues were observed: Access roads not accessible or maintained to get to well. Location is within a designated setback location, maintain and repair access roads per Rule 204. Corrective Action Date 30 days. See attached photo #1. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	10/15/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402854274	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5565049

700900796	Inspection photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5565037
-----------	------------------	---