


---

**From:** Ally Ota <Alexandria.Ota@pdce.com>  
**Sent:** Wednesday, October 27, 2021 8:52 AM  
**To:** Acks - DNR, Alex  
**Cc:** Venessa Chase; Cassie Gonzalez  
**Subject:** FW: [EXTERNAL] :Harold 6Y-312 Base of Productive Zone

Good Morning Alex,

You are correct, this spacing unit was extremely tight and this small deviation from plan to drill caused us to pull in the NWNW of Section 10. We are working with outside council to get a DSU for this well submitted.

Please let me know if you need anything further from us at this time.

 Ally Ota | Regulatory Analyst | PDC Energy, Inc. | O: 303-831-3931 | C: 435-671-7477

---

**From:** Cassie Gonzalez <Cassie.Gonzalez@pdce.com>  
**Sent:** Tuesday, October 19, 2021 4:11 PM  
**To:** Ally Ota <Alexandria.Ota@pdce.com>  
**Subject:** FW: [EXTERNAL] :Harold 6Y-312 Base of Productive Zone

 Cassie Gonzalez | Regulatory Analyst | PDC Energy, Inc. | O: 303-381-9329 | [Cassie.Gonzalez@pdce.com](mailto:Cassie.Gonzalez@pdce.com)

---

**From:** Acks - DNR, Alex <[alex.acks@state.co.us](mailto:alex.acks@state.co.us)>  
**Sent:** Tuesday, October 19, 2021 4:00 PM  
**To:** Cassie Gonzalez <[Cassie.Gonzalez@pdce.com](mailto:Cassie.Gonzalez@pdce.com)>  
**Subject:** [EXTERNAL] :Harold 6Y-312 Base of Productive Zone

Hi Cassie -

I am concerned about the BPZ on this well, Harold 6Y-312 (API 123-45752). The WSU as approved was extremely tight and the BHL/BPZ ended up 14' further south than planned.

Please confirm the BPZ/BHL with validated data such as a survey plat to show that the 460' WSU setback hasn't been pushed into NWNW Section 10 4N 64W by the completion.

--

**Alex Acks**

**Permit and Completions Specialist**

Pronouns: They/Them



P 303.894.2100 x 5135

[1120 Lincoln Street, Suite 801, Denver, CO 80203](#)

[alex.acks@state.co.us](mailto:alex.acks@state.co.us) / [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)