

# Inspection Photos

Operator: Logos Operating  
API: 067-09595  
Date: 10/29/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Vegetation is sparse and needs to be assessed during the active growing season.





Photo 3. View of erosional rilling and sediment deposition on the well pad cut-slope. Bare soils need erosion controls until stabilized with desirable perennial vegetation.





Photo 4. View of reference area comprised of open grass field with grasses largely in a grazed condition.