

TEP
Clough 332-21
Location # 335340



location



location

TEP
Clough 332-21
Location # 335340




location



Load line missing bull plug/cap

TEP
Clough 332-21
Location # 335340



Load line missing bull plug/cap



Lack of stabilization/erosion

TEP
Clough 332-21
Location # 335340



Lack of stabilization/erosion



Lack of stabilization/erosion



TEP
Clough 332-21
Location # 335340



Lack of stabilization/erosion

