

TEP
RMV 10-22
Location # 335175



location



location

TEP
RMV 10-22
Location # 335175



location



Glycol vessel lacking labeling



TEP
RMV 10-22
Location # 335175



Load line missing bull plug/cap



Load line missing bull plug/cap

TEP
RMV 10-22
Location # 335175



Lack of stabilization/compaction



Lack of stabilization/compaction

