

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/02/2021

Submitted Date:

11/02/2021

Document Number:

693505721

FIELD INSPECTION FORM

Loc ID 318576 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
,	303-825-4822	cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241640	WELL	PR	02/01/2020	OW	123-09429	UPRR 43 PAN AM B 6	PR

General Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 241640 Type: WELL API Number: 123-09429 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 11/04/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday November 2, 2021 at approximately 11:22, I, Inspector Randy Silver, conducted an on-site inspection. Location: UPRR 43 Pan AM #6 Operator: KP Kauffman API#:12309430 County: Weld While there, I observed what appeared to be a producing well site. During this inspection the following possible compliance issues were observed: Well head sign: Rule 605 g Corrective action date of 12-2-21 See photo 2 Operator had been warned in inspection document #693502639 sign was fading and needed to be replaced. Weather conditions: Cloudy and wet A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	11/02/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402860033	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5570189
693505722	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5570179