

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/14/2021

Submitted Date:

11/01/2021

Document Number:

700900832

FIELD INSPECTION FORMLoc ID 319690 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
,		rwatzman@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
200886	WELL	PR	09/01/2020	GW	001-06289	UPRR 23 PAN AM D 1	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds throughout location.		
Corrective Action:	Weeds throughout location. Location is within a designated setback location, remove trash, debris and weeds per Rule 606. Corrective Action Date 11/19/2021. See attached photo #1 through 3	Date:	11/19/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appeared to be plumbed to surface		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		39.933118,-104.564952	
Comment:	Stained soil around tank.					
Corrective Action:	Stained soil around tank. Control and contain spills/releases and clean up per Rule 912.aContact COGCC EPS staff. Immediately to stop and clean up 24 hours to remove free fluids. . Corrective Action Date 12/10/2021 to remove stained soil. See attached photo #4 through 6					Date: 12/10/2021

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Wells Served By Facilities Above**AirsID**

API Number
001-06289

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 200886 Type: WELL API Number: 001-06289 Status: PR Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Appears to be plumbed to surface

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday October 14, 2021 at approximately (). I, Inspector Chane Finkenbinder, Conducted an on-site inspection at Upr 23 Pan Am D, KP Kaufmann, at API # 001-07499 in Adams County Colorado.</p> <p>While there, I observed a shut in well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds throughout location. Location is within a designated setback location, remove trash, debris and weeds per Rule 606. Corrective Action Date 11/19/2021. See attached photo #1 through 3</p> <p>Stained soil around tank. Control and contain spills/releases and clean up per Rule 912.aContact COGCC EPS staff. Immediately to stop and clean up 24 hours to remove free fluids. . Corrective Action Date 12/10/2021 to remove stained soil. See attached photo #4 through 6</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	finkenbc	11/01/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402859814	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5569961
700900833	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5569953