

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/03/2021

Submitted Date:

11/05/2021

Document Number:

690202251**FIELD INSPECTION FORM**Loc ID 333395 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-------------------------|-------|----------------------------|---------|
| Distribution, Evergreen | | cogcc.evergreen@enrllc.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 272038 | WELL | PR | 08/24/2004 | GW | 071-08046 | RIVERTON 14-21 | PR |

General Comment:

This is a Stormwater Management Inspection.
See attached photos and additional details within this report.

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|--|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |
| <p>Comment: There are areas of erosion along the access road and a culvert is filled in with sediment. Areas of erosion need to be repaired and stabilized. Disturbance near the location needs to be reclaimed.</p> <p>Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C</p> <p>Date: 11/26/2021</p> | | | | | | |
| <p>Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT</p> | | | | | | |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402863479 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5573518 |
| 690202252 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5573514 |