

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/29/2021

Submitted Date:

07/30/2021

Document Number:

693903486**FIELD INSPECTION FORM**Loc ID 312051 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10679Name of Operator: LOGOS OPERATING LLCAddress: 2010 AFTON PLACECity: FARMINGTON State: NM Zip: 87401**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Hughes, Jim		jimo.hughes@state.co.us	
Arthur, Denise		denise.arthur@state.co.us	
Rowley, Darren		drowley@logosresourcesllc.com	All inspections
Sessions, Tamra		tsessions@logosresourcesllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216532	WELL	TA	05/01/2019	GW	067-08138	BONDAD 33-9 22A	RI

General Comment:

On 7/29/2021 Catherine Roy conducted a reclamation and stormwater inspection. It is apparent that recent precipitation has resulted in flood/stormwater transport across the well pad. During this inspection the following compliance issues were observed:

-Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff per Rule 912.b. by within 24 hours of receiving this report (7/31/2021). Remove any free fluids within 24 hours of receiving this report (7/31/2021), and submit a Form 19 within 72 hours of receiving this report (8/2/2021).

-Remove and properly manage gravel, rock, and material displaced and discharged downslope of the well pad. Remove and properly dispose of debris deposited on well pad and around facilities. Submit (as an attachment to a Form 4) and implement a plan to properly divert and protect the location from degradation during significant stormwater events on the well pad using good engineering practices. All inlets and outlets need to be properly designed and constructed to ensure stabilization. Corrective action date is the day of the inspection (7/29/2021) as it is required that the corrective action be addressed immediately.

-Per Rule 421.b. for wells within the 100 year floodplane submit as an attachment to a Form 4, Operator's Flood Shut-In Plan by 8/2/2021.

This is a shared location between Simcoe and Logos. It is the responsibility of both operator's to ensure compliance with COGCC rules.

Per communication with Steve Labowskie on 7/29/2021, Operator was contacted and notified of issues observed at this time.

See below, and attached photos for additional detail.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type:	#		corrective date
Comment:			
Corrective Action:	-Per Rule 421.b. for wells within the 100 year floodplane submit as an attachment to a Form 4, Operator's Flood Shut-In Plan by 8/2/2021.		Date: <u>08/02/2021</u>

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: **-Buried vessel full with woody debris floating. Puddles of oily black material observed within and outside of containment.**Corrective Action: **-Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff per Rule 912.b. by within 24 hours of receiving this report (7/31/2021). Remove any free fluids within 24 hours of receiving this report (7/31/2021), and submit a Form 19 within 72 hours of receiving this report (8/2/2021). Contact Jim Hughes (970) 903-4072**Date: 07/31/2021

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Large volumes of well pad material is washed downslope from the well pad and likely into the Florida River. Debris is deposited around well facilities.

Corrective Action: -Remove and properly manage gravel, rock, and material displaced and discharged downslope of the well pad. Remove and properly dispose of debris deposited on well pad and around facilities. Submit (as an attachment to a Form 4) and implement a plan to properly divert and protect the location from degradation during significant stormwater events on the well pad using good engineering practices. All inlets and outlets need to be properly designed and constructed to ensure stabilization. Corrective action date is the day of the inspection (7/29/2021) as it is required that the corrective action be addressed immediately.

Date: 07/29/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402766562	INSPECTION SUBMITTED	https://cogcc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=5494726
693903486	INSPECTION APPROVED	https://cogcc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=5499623
693903488	Inspection Photos	https://cogcc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=5494723