

TEP
Left Fork P36-299
Location # 316511



location



location

TEP
Left Fork P36-299
Location # 316511



location



Chemical tank lacking labeling

TEP
Left Fork P36-299
Location # 316511



Chemical tank lacking labeling



Glycol vessel lacking labeling

TEP
Left Fork P36-299
Location # 316511



location



Load out lines lacking bull plugs/caps

TEP
Left Fork P36-299
Location # 316511



Load out lines lacking bull plugs/caps



Load out lines lacking bull plugs/caps and possible slow leak

TEP
Left Fork P36-299
Location # 316511



Load out lines lacking bull plugs/caps



Staining

TEP
Left Fork P36-299
Location # 316511



Access road lack of stabilization/erosion

