

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402786821

Date Received:

09/14/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10766

Name of Operator: ARKOMA OPERATIONS LLC

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Andrew Price

918-965-0044

aprice@arkomaops.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903527

Inspection Date: 08/06/2021

FIR Submit Date: 08/12/2021

FIR Status: _____

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC

Company Number: 10464

Address: 1001 17TH STREET STE 1160

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 325139

Location Name: HELTON MVRD GAS UNIT-N3N8W Number: 18NESE County: LA PLATA

Qtrqr: NESE Sec: 18 Twp: 33N Range: 8W Meridian: N

Latitude: 37.101300 Longitude: -107.753530

FACILITY - API Number: 05-067-00 Facility ID: 214104

Facility Name: HELTON MVRD GAS UNIT Number: 1

Qtrqr: NESE Sec: 18 Twp: 33N Range: 8W Meridian: N

Latitude: 37.101300 Longitude: -107.753530

CORRECTIVE ACTIONS:

1 ☒ CA# 154778

Corrective Action: -Stormwater (ie: BMPs) and erosion controls (ie: erosion control blanket, hydromulch, etc.) need to be installed to stabilize erosion and prevent sediment discharge within the project area, no later than 9/12/2021. Controls need to be selected, sized, installed, and maintained according to good engineering practices such as those described by CDOT in their erosion control manuals.

Date: 09/12/2021

Response: CA COMPLETED

Date of Completion: 09/02/2021

Removed non functioning wattles and installed a drainage ditch to divert storm water into a natural drainage on the western edge of the location, filled in channels and rills. Reseeded the bare cut slope. Installed a drainage ditch at the top of Eastern fill slope, filled in channels and rills, reseeded the berm and slope.

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed: _____

Title: Engineering Analyst

Date: 9/14/2021 8:50:38 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402786821	FIR RESOLUTION SUBMITTED
402810054	Helton 1 9-12-21 (690903527) remedial report

Total Attach: 2 Files