

**WELL ABANDONMENT REPORT**

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

Document Number:  
 402847788  
 Date Received:  
 10/25/2021

OGCC Operator Number: 10661 Contact Name: Abigail Wenk  
 Name of Operator: BISON OIL & GAS II LLC Phone: (720) 644 6997  
 Address: 518 17TH STREET #1800 Fax: \_\_\_\_\_  
 City: DENVER State: CO Zip: 80202 Email: awenk@bisonog.com

**For "Intent" 24 hour notice required,** Name: Petrie, Erica Tel: (303) 726-3822  
**COGCC contact:** Email: erica.petrie@state.co.us

Type of Well Abandonment Report:  Notice of Intent to Abandon  Subsequent Report of Abandonment

API Number 05-123-05464-00  
 Well Name: DUELL-CAMPBELL Well Number: 1  
 Location: QtrQtr: W2 Section: 31 Township: 8N Range: 59W Meridian: 6  
 County: WELD Federal, Indian or State Lease Number: \_\_\_\_\_  
 Field Name: WILDCAT Field Number: 99999

*Only Complete the Following Background Information for Intent to Abandon*

Latitude: 40.618847 Longitude: -104.028013  
 GPS Data: GPS Quality Value: 1.4 Type of GPS Quality Value: PDOP Date of Measurement: 08/04/2021  
 Reason for Abandonment:  Dry  Production Sub-economic  Mechanical Problems  
 Other Re-enter to Replug  
 Casing to be pulled:  Yes  No Estimated Depth: \_\_\_\_\_  
 Fish in Hole:  Yes  No If yes, explain details below  
 Wellbore has Uncemented Casing leaks:  Yes  No If yes, explain details below  
 Details: \_\_\_\_\_

**Current and Previously Abandoned Zones**

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth

Total: 0 zone(s)

**Casing History**

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	15	10+3/4	unknow	32.75	0	263	150	275	0	VISU
OPEN HOLE	8+3/4				263	6930				

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 121 sks cmt from 6185 ft. to 5885 ft. Plug Type: OPEN HOLE Plug Tagged:   
Set 61 sks cmt from 1650 ft. to 1500 ft. Plug Type: OPEN HOLE Plug Tagged:   
Set 84 sks cmt from 6930 ft. to 6725 ft. Plug Type: OPEN HOLE Plug Tagged:   
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged:   
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged:   
Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
(Cast Iron Cement Retainer Depth)  
Set 301 sacks half in. half out surface casing from 600 ft. to 0 ft. Plug Tagged:   
Set \_\_\_\_\_ sacks at surface  
Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker:  Yes  No  
Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing Number of Days from Setting Surface Plug to Capping or Sealing the Well: \_\_\_\_\_  
Surface Plug Setting Date: \_\_\_\_\_ Cut and Cap Date: \_\_\_\_\_  
\*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: \_\_\_\_\_  
Type of Cement and Additives Used: \_\_\_\_\_  
Flowline/Pipeline has been abandoned per Rule 1105  Yes  No

#### Technical Detail/Comments:

If Nio tag is deeper than 5985', Operator will contact COGCC Engineer to discuss setting additional cement for Nio coverage. Purpose is to re-enter and adequately re-plug prior to hydraulic stimulation of proposed horizontal well per DJ Basin Offset Policy, dated December 16, 2013. Closed loop system will be used.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Abigail Wenk  
Title: Manager of Compliance Date: 10/25/2021 Email: awenk@bisonog.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Wolfe, Stephen Date: 12/3/2021

#### CONDITIONS OF APPROVAL, IF ANY:

Expiration Date: 6/2/2022

## Condition of Approval

### COA Type

### Description

	<p>Plugging</p> <ol style="list-style-type: none"> <li>1) Provide 48 hour notice of plugging MIRU via electronic Form 42.</li> <li>2) Contact COGCC Area Inspector prior to commencing plugging operations.</li> <li>3) Plugs and squeezes will be placed as stated in the Plugging Procedure section of the approved NOIA unless revised by COA or prior approval from COGCC is obtained.</li> <li>4) The wellbore must be static prior to placing cement plugs which are to be a minimum of 100' in length for all but surface plugs. Mechanical isolation requires a 25' cement plug, minimum. For plugs not specified to be tagged, a tag is required if circulation is not maintained while pumping plug and displacing to depth. Tag at tops specified or shallower. Notify COGCC Area Engineer before adding cement to previous plug.</li> <li>5) Place a 50' plug (minimum) at the surface, both inside the inner most casing and in all annular spaces. Surface plugs shall be circulated to surface. Confirm cement to surface in all strings during cut and cap.</li> <li>6) With the Form 6 SRA operator must provide written documentation which positively affirms each COA has been addressed.</li> <li>7) Add 84 sx plug at 6930-6725' to isolate J and D sands.</li> <li>8) After placing the shallowest hydrocarbon isolating plug (6185-5885'), operator must wait a sufficient time on all subsequent plugs to confirm static conditions. If at any time after placing this plug there is evidence of pressure or of fluid migration, contact COGCC Area Engineer before continuing operations.</li> <li>9) After pumping plug at 1650-1500' WOC and tag at 1500' or shallower.</li> <li>10) Increase plug at 550-0' to 600-0', adjust cement volume accordingly. Plug is intended to circulate to the surface and stay there. Tag is required if this is not the case before adding cement to bring cement to the surface.</li> </ol>
	Operator will implement measures to capture, combust, or control emissions to protect health and safety, and to ensure that vapors and odors from well plugging operations do not constitute a nuisance or hazard to public health, welfare and the environment.
2 COAs	

## Attachment List

### Att Doc Num

### Name

402847788	FORM 6 INTENT SUBMITTED
402847809	PROPOSED PLUGGING PROCEDURE
402847811	WELLBORE DIAGRAM
402847812	WELLBORE DIAGRAM
402848760	LOCATION PHOTO
402848836	SURFACE OWNER CONSENT

Total Attach: 6 Files

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	Groundwater: Laramie-Fox Hills, Upper Pierre Deepest Water Well: 450(1mi)+4950-4920=480' , 1525(2mi)+4950-4940=1535' Log: 123-05491 2/28/56 GR 4930 4950-4930=+20' L-FH base 524+20=544', UP (830-1530')+20=850-1550'	12/03/2021
OGLA	This oil and gas location is within CPW mapped Pronghorn Winter Concentration Area High Priority Habitat. CPW recommends that plugging and abandonment (PA) activities should not take place from January 1 to April 30.	11/17/2021
Permit	-GPS data plots the surface location 55' away from COGCC records but updated GPS data was taken recently by the operator -Well was never completed via Doc 817266 -No production report to verify -Operator will implement measures to capture, combust, or control emissions to protect health and safety, and to ensure that vapors and odors from well plugging operations do not constitute a nuisance or hazard to public health, welfare and the environment. Due to proximity of building units (BUs) all blowdown gases will be controlled. Due to close proximity to Residential Building Units: prior to commencing operations, at a minimum, the operator will provide an informational sheet to the owners/occupants of BUs that are nearby and adjacent to the parcel on which the well is located. The sheet will include the operator's contact information and the nature, timing, and expected duration of the PA operations. assed Permit Review	10/28/2021

Total: 3 comment(s)