

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/01/2021

Submitted Date:

12/07/2021

Document Number:

690202330

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 83130  
Name of Operator: STRACHAN EXPLORATION INC  
Address: 383 INVERNESS PKWY, STE 360  
City: ENGLEWOOD State: CO Zip: 80112

**Findings:**

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
BEAR STACY		stacy@strachanexploration.com	
STRACHAN STEVEN		sms@strachanexploration.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431431	GAS COMPRESSOR STATION	AC			-	Prowers Gas Gathering Co Fluid tank 431431	RI
448842	PIPELINE	AC	12/21/2016		-	PROWERS GAS GATHERING LINE	RI

**General Comment:**

This is a follow up location inspection of the Prowers Gas Gathering Co Fluid tank/431431. See attached photos and additional details within this report.

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	Sign has been installed.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Labels posted on tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

**Good Housekeeping:**

Type	OTHER		
Comment:	There is oil and trash stored inside the secondary containment. No wildlife protection to prevent entry. Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906.		
Corrective Action:	Immediately clean up and properly dispose. Comply with Rule 606	Date:	12/08/2021

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	

Comment: There is still oil stained soil around the compressor and oily rags on the compressor skid.

Corrective Action: Immediately Conduct maintenance on equipment, cleanup stained material and review self inspection processes.  
Implement or modify BMPs for improved material handling and spill prevention.

Date: 01/22/2021

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690202331	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5599521">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5599521</a>