

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402897324

Date Received:

12/13/2021

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

GEE, GREG

ggee@ogrisop.com

ATWATER BONNIE

batwater@ogrisop.com

Fitzgerald, Edie

efitzgerald@ogrisop.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690202344

Inspection Date: 12/08/2021

FIR Submit Date: 12/08/2021

FIR Status: _____

Inspected Operator Information:

Company Name: OGRIS OPERATING LLC

Company Number: 10758

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

LOCATION - Location ID: 308792

Location Name: GOLDEN EAGLE-633S67W Number: 20SWNW County: LAS ANIMAS

Qtrqr: SWN Sec: 20 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.160570 Longitude: -104.915560

FACILITY - API Number: 05-071-00 Facility ID: 281760

Facility Name: GOLDEN EAGLE Number: 20-5X

Qtrqr: SWN Sec: 20 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.160570 Longitude: -104.915560

CORRECTIVE ACTIONS:

1 CA# 158454

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 12/10/2021

Response: CA COMPLETED

Date of Completion: 12/09/2021

THE STAINED SOIL WAS REMOVED. THE GROUND IS CLEAN AND NO ENVIRONMENTAL IMPACTS WERE DISCOVERED.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 158455

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 01/08/2022

Response: CA COMPLETED

Date of Completion: 12/13/2021

Operator
Comment:

THE SOURCE OF THE WATER THAT WAS FOUND ON THE ROAD SURFACE IS FROM A NATURAL SPRING THAT FLOWS YEAR ROUND ADJACENT TO THE LEASE ROAD. THE VEGETATED BAR DITCH WAS DOMINATED TO RECEIVE WATER FROM THE SPRING. THIS FLOWS DOWN TO THE EPHEMERAL CHANNEL NORTH OF THE GE 20-05X WELL PAD.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. SEE ATTACHED PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed:

Title: Sr. Environmental Tech.

Date: 12/13/2021 4:19:09 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402897332	PHOTO LOG
-----------	-----------

Total Attach: 1 Files