

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402897878

Date Received:
12/14/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 6 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10663
Name of Operator: ENDURING RESOURCES LLC
Address: 6300 S SYRACUSE WAY, SUITE 525
City: CENTENNIAL State: CO Zip: 80111

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Walter, Kyle</u>		<u>kwalter@enduringresources.com</u>
<u>Huntington, Heather</u>		<u>hhuntington@enduringresources.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 688801000
Inspection Date: 09/16/2021 FIR Submit Date: 09/17/2021 FIR Status: _____

Inspected Operator Information:

Company Name: ENDURING RESOURCES LLC Company Number: 10663
Address: 1050 17TH STREET SUITE 2500
City: DENVER State: CO Zip: 80265

LOCATION - Location ID: _____

Location Name: _____ Number: _____ County: _____
Qtrqr: NENE Sec: 27 Twp: 33N Range: 9W Meridian: N
Latitude: 37.079137 Longitude: -107.808067

FACILITY - API Number: 05-067-00 Facility ID: 480754

Facility Name: Southern Ute 16 Produced Water Tank Number: _____
Qtrqr: NENE Sec: 27 Twp: 33N Range: 9W Meridian: N
Latitude: 37.079137 Longitude: -107.808067

CORRECTIVE ACTIONS:

1 CA# 155956

Corrective Action: Install liner material to ensure spill or released materials will be maintained within containment structure. Comply with Rule 603.o. Date: 10/18/2021

Response: CA COMPLETED Date of Completion: 12/10/2021

Operator Comment: Liner material cannot be installed until we receive soil samples back to ensure the spill has been adequately cleaned up per regulations. Liner material will be installed once we receive the all clear. UPDATE- liner material and tank reinstalled upon clean 12/14/21 UPDATE- Spill cleanup complete and the liner and tank have been

reinstalled and are in operation

COGCC Decision: Approved via an AMI

COGCC Representative:

[Empty text box for COGCC Representative]

3 CA# 155958

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a

Date: 10/18/2021

Response: CA COMPLETED

Date of Completion: 12/10/2021

Operator Comment: Spill was controlled and contained upon discovery of the release as noted in the Form 19 filed. Clean up is ongoing and waiting on soil sample results in order to determine if more clean up is needed. All spill reporting required is being done via Form 19 as per COGCC regulations.12/14/21 UPDATE- Spill cleanup complete

COGCC Decision: Approved

COGCC Representative:

[Empty text box for COGCC Representative]

4 CA# 155959

Corrective Action: Comply with Rule 606

Date: 10/18/2021

Response: CA COMPLETED

Date of Completion: 12/10/2021

Operator Comment: The chemical injection system containers near pump jack cannot be reinstalled until we have completed the tank repair and the chemical pump repair is completed. The stainless steel tubing protruding has been cleaned up, see picture attached. 12/14/21 UPDATE- Spill cleanup complete and the chemical injection system has been reinstalled and is in operation

COGCC Decision: Approved

COGCC Representative:

[Empty text box for COGCC Representative]

OPERATOR COMMENT AND SUBMITTAL

Comment: See attached pictures of tank/liner and chemical injection system placed back into service.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Heather Huntington Signed: _____

Title: Permitting Technician Date: 12/14/2021 10:42:14 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402897878	FIR RESOLUTION SUBMITTED
402897937	follow up photos

Total Attach: 2 Files