

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Emergency number is not legible. See attached photos.		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: 01/20/2022
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		
Date: _____			
Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil at wellhead. See attached photos.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.(2).d.		Date: 01/20/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	6' chain link		
Corrective Action:			
			Date:
Equipment:			
			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 243187 Type: WELL API Number: 123-10978 Status: SI Insp. Status: SI**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: Corrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary **Weather Conditions: sunny, dry ground On Monday, December 20, 2021 at approximately 14:15, I, Inspector Brittani Santistevan, conducted an on-site inspection at BUNN 1-35 (PDC Energy), at API: 05-123-10978 in WELD COUNTY Colorado. While there, I observed a shut in wellhead. During this inspection the following possible compliance issues were observed: 1. The emergency number posted on wellhead sign is no longer legible. Install new sign to comply with Rule 605.d. (Corrective Action Date: January 20, 2022) See attached photo #1. 2. Stained soil at wellhead. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002(2).d. (Corrective Action Date: January 20, 2022) See attached photos #3, 4.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	12/20/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402906596	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5614278
679604332	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5614234