

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402885889

Date Received:  
12/28/2021

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
Rowley, Darren	505-947-4974	drowley@logosresourcesllc.com
Trujillo, Etta		etrujillo@logosresourcesllc.com
Florez, Marie		mflorez@logosresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700300298

Inspection Date: 11/09/2021

FIR Submit Date: 11/11/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

LOCATION - Location ID: 325204

Location Name: BONDAD 33-10-N33N10W Number: 3SESE County: LA PLATA

Qtrqtr: SESE Sec: 3 Twp: 33N Range: 10W Meridian: N

Latitude: 37.128430 Longitude: -107.917970

FACILITY - API Number: 05-067-00 Facility ID: 214267

Facility Name: BONDAD 33-10 Number: 4

Qtrqtr: SESE Sec: 3 Twp: 33N Range: 10W Meridian: N

Latitude: 37.128430 Longitude: -107.917970

CORRECTIVE ACTIONS:

1 CA# 157711

Corrective Action: Retroactively submit electronic from 42 notice of well liquids unloading

Date: 11/12/2021

Response: CA COMPLETED

Date of Completion: 12/02/2021

Operator Comment: LOGOS submitted a Form 42 due to unloading the well manually and pumper was unaware of the process. LOGOS reviewed rules 405.s and 903.d (1) and regulatory met with the pumper to ensure this would not occur again.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

--

**OPERATOR COMMENT AND SUBMITTAL**

Comment: LOGOS submitted a Form 42 due to unloading the well manually and pumper was unaware of the process. LOGOS reviewed rules 405.s and 903.d (1) and regulatory met with the pumper to ensure this would not occur again.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Marie E. Florez

Signed: \_\_\_\_\_

Title: Regulatory Specialist

Date: 12/28/2021 6:02:40 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

402885909	Form 42
-----------	---------

Total Attach: 1 Files