



00250985

DO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORTRECEIVED
SEP 7 1995☐ NOTICE OF UNSATISFACTORY INSPECTION☒ NOTICE OF SATISFACTORY INSPECTION.1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100

API No. 05- 075 - 06524

LEASE NAME: Henderson 5

LOCATION: SWNW 18-9N-53

OPERATOR: Walsh

DATE: 8-28-95

INSPECTOR: Ed Binley

Insp. Type: 12

Insp. Status: SI

PA: Y N

Pass/Fail: P F

Viol.: Y N

NOV: Y N

INSPECTION ITEM

COMMENTS

INPUT

Well ID Signs (Rule 210)		
Pits (Reserve/Production) (Rule 902, 903, 904)		
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)		
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)	pump jack	
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)		
Miscellaneous	Submit Change of operator. Form 10 Evaluate well for MIT, Rule 3246.	

CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site